

Moisture and Housing Research at USDA - FPL

Charles Carll
Anton TenWolde



Areas

- Moisture-related properties of wood products
- Moisture accumulation in light-frame walls:
Effects of
 - air leakage
 - indoor moisture loads
 - wall design

This presentation concerns



Research/Demonstration [Demonstration/Research] House
Industry funded - - show that if there aren't stupid construction errors, contemporary wood-framed houses are durable

House characteristics

- Contemporary design
 - has some features that are less than ideal from a water-management perspective
- AWWF (CCA-treated lumber and plywood)
- 2x6 walls (OSB-sheathed & cellulose-insulated)
 - Damp spray - no interior vapor retarder (for the most part)
- Garage walls and ceiling insulated (and drywalled)
- Various cladding systems
- Sealed combustion gas furnace
- Energy recovery ventilator
 - Exhaust air from bathrooms: makeup air into return ducting

House air-tightness/leakiness

- **ACH50 of 4.3** (common mode testing: garage door(s) closed – both overhead and house/garage passage)
 - Roughly equivalent to 60% of the houses (that we've tested) constructed in the 537XX Zip-code since 1990
 - ACH50 of 4.3 = 1300 cfm50, of which 350 cfm was directly thru envelope and 950 cfm was thru series-attached zones

Site conditions

- Reasonably dry
 - (flooding potential aside from backed-up gutter - nil)
- Cold climate (7400 HDD - - historically)
 - Oct 2001 - May 2002: 6214 HDD
 - Sept 2002 - May 2003: 7471 HDD
 - Sept 2003 - May 2004: 6971 HDD
 - Sept 2004 - May 2005: 6545 HDD
 - Sept 2005 – Apr 2006: 6229 HDD
- Winters not as cold as they used to be, but still > 5400 HDD - - - the DOE Building America definition of a cold climate

Construction history

- Damp spray cellulose installed 6/19/01
 - Building weather-tight, (roof functional, windows in, and WRB over wall sheathing, but cladding not yet installed)
- Drywalled 6/29 – 7/1/01
- Painted (interior latex flat) late August '01
- Spray moisture had dissipated by time of painting
- Tyvek WRB (very vapor permeable):
 - Various claddings installed late July to late Sept '01
- Gutter installation late Sept. '01
- Landscape grading Oct. '01

Operational history preview

- Eight instrumented wall cavities (above grade)
- Instrumentation in clear-field walls
 - Garage had largest expanse of clear-field wall
- Garage sidewall was the only one with stucco cladding
- Thus for all heating seasons, garage was conditioned like interior space (and wasn't isolated from the house during AC seasons)

Operational history: by heating season

- 2001/02: No humidification or (intentional) ERV
- 2002/03: No humidification or (intentional) ERV
- 2003/04: Design humidity (monthly set-points)
- 2004/05: Design humidity (monthly set-points)
- 2005/06: Garage isolated from house:
 - Garage: design humidity level (as before)
 - House design load (10 Liters/day release), and run ERV 20 minutes each hour
- Building AC'ed (75° F setpoint) in summer
- May thru October: daily 15-minute public tour

Design humidity levels: (monthly setpoints)

- Based on calculation methodology of ASHRAE Draft Standard 160-P
 - Design value (above average loads)
 - Based on the following assumptions
 - Higher than average interior moisture sources (14.2 L/day)
 - Moderate in-use air-exchange ratio (0.2 ACH) (equivalent to 60 cfm for 18,200 ft³ inter. vol. - - - coincidentally the vent rate recommended by ASHRAE Std. 62.2 for acceptable IAQ in a 2200 ft² 3 BR home)
- 10th percentile in terms of humidity level
 - For the aggregate existing housing stock, one house in ten will have higher winter indoor RH levels. For **New** houses, it's probably more like one in three?

The Interior RH Levels

- Oct: 66%
- Nov: 54%
- Dec: 45%
- Jan: 43%
- Feb: 43%
- Mar: 50%
- Apr: 59%
- Correspond with 8.2% -12.2% EMC (4% seasonal mc swing ignoring sorption hysteresis) - - - Nice for finish floors and furniture

The first two heating seasons

(no occupants, no humidification, 65° F)

- Interior vapor pressures were at roughly 85% of those that would correspond with those at design temp/RH levels
 - Landscape grading and guttering in the construction sequence (H_2O in sump)
 - Sealed-combustion furnace (ACH probably < 0.2 when ERV isn't enabled)




Heavy condensation
on mediocre IGU's
when outdoor temp
fell below 10° F


But condensation
only on glass - - -
No water on, or
staining of, sash



Minor condensation on high-performance IGU's at similar outdoor temps - - - suggesting that indoor RH levels really were reasonable




Flat-grain lumber porch ceiling
buckled from accumulated
condensation.
OSB siding did not.




Note location of buckles relative to exterior walls and cantilevered floor.
Attic remained dry - - - we checked

Minor cracking of exterior stucco,
which is consistent with dimensional
movement of the OSB sheathing



humidifier trends



Shows that humidifier input to maintain set-points was inversely related to outdoor temp (as expected), and that humidifier input was usually less than 14 L /day - - In short, it usually didn't take as much water to reach set-points as calculated (remember that 0.2 ACH vent rate was assumed by calcs)



What happened (in the sheathing) inside the walls?

Instrumented walls

- Brick veneer (spaced) (NW)
- OSB lap siding (NE)
 - Not furred and furred w.o. vent openings
- Plywood panel (not furred) (SE)
 - x two
- Lime-Portland-Cement plaster (SW)
 - x two (plus one with interior polyethylene)



Shows that the spaced siding was only spaced - - not ventilated. Soffit facing was on before furring strips went up.

Finding 1

- Disturbingly high sheathing mc levels by February occurred in all walls (except the one with interior polyeth) in all heating seasons (even the first two - - w.o. any humidification)

Opened a (non-instrumented) wall toward end of 4th heating season






Saint Patty's Day 2005

Finding 2


Interior polyeth sheet kept the sheathing dry

2005 mc wk av



g5 is the wall with the interior vapor retarder.

2005 rh wk av



Sheathing mc and within-cavity RH, near the sheathing, show similar trends


Considerations re Finding 2

- Poly wall was SW-facing and stucco-clad (the other stucco-clad instrumented wall spaces were SW-facing too)
- But it was 1-story with modest roof overhang and functioning gutter
- The influence of poly (which was distinctly beneficial on this building wall) might not be so beneficial in another climate - - - or in a stucco-clad wall with significant windblown rain exposure

Finding 3


- Contemporary latex vapor retarding paint was not as effective as polyeth sheet, but it definitely helped.

2005 mc wk av




Walls g2 and g3 got a coat of vapor retarder paint in early Oct. 2005

2006 mc wk av




Findings 4a and 4b

- Spacing the cladding out from the sheathing resulted in more rapid springtime moisture dissipation.
- Sheathing on north-facing walls behind spaced brick or spaced OSB lap siding had more favorable moisture history than sheathing on south-facing walls behind unspaced plywood panel siding or behind stucco.



Wall 2 had unspaced OSB siding.

Walls 1 and 3 had spaced brick and OSB claddings, respectively



Springtime reduction in within-cavity RH was slower when cladding wasn't spaced

Conclusion(s)

- At design interior conditions, in a 6800 HDD climate, lack of an interior vapor retarder results in wintertime moisture accumulation in OSB sheathing (at least in 2x6 walls), - - -
- - sufficient for a 16% mc max in-service value (assumed by the APA Engineered Wood Handbook) to be exceeded.
- Spacing the cladding out from the WRB appears to be helpful

Parting idea re Conclusion 1

- “We worry about sheathing getting wet during the winter, but it rots during the summer”.
- This quote is factual, but 1980’s experience indicates that decay fungi can eventually do their (destructive) thing to sheathing on winter-accumulated moisture each spring (incrementally - - year by year) - - - unless springtime dissipation is rapid.

The traditional reason for installing a vapor retarder was exterior paint performance - - - that's not necessarily the case now



Acknowledgements

- APA
- SFPA
- Collin Olson of the Energy Conservatory
- Mark Knaebe, Bob Munson, and Joe Murphy of FPL